



LINEAR **M**EASUREMENT **I**NSTRUMENTS, Corp.

Research, Development and Manufacturing of Precision Measuring Systems

**CALIBRATION/ MASTERING INSTRUCTIONS FOR LMI 770
TO INTERFACE WITH DATAMYTE 3053**

REQUIRED EQUIPMENT FROM DATAMYTE: DataMyte 3053

REQUIRED EQUIPMENT FROM LMI:

- LMI 770 Series Flush/Gap Transducer
- LMI 720 Master Block
- LMI 6100 Interface which includes:
 - LMI 6009 4 pin to 4 pin cable
 - LMI 6011 6 pin to 8 pin cable
 - LMI 6007 Interface Control Unit
 - LMI 6002 Modular Adaptor

SET UP FOR FLUSHNESS:

1. Connect the transducer to Gage Port 1 of the data collector.
2. Turn on the data collector.
3. Move the cursor to "Options".
4. Select "Configure Gages" and press "Enter".
5. From the list displayed use the arrow keys on the data collector to choose which gage designation to configure, (i.e., G1, G1A) and press "Enter".
6. Type the unique gage name, (i.e.: LMI-FLUSH) and press "Enter".
7. Move the cursor to "Configure" and set up as follows:
 - Type: Gap & Flush
 - Scale: 10
 - Zero Master: 0
 - Transducer: Low level gap gage
 - Switch: (Read)
 - Master Type: (Three point)
 - Show Additional Parameters: (No)
8. Press the right arrow key. A "Save Gage Configuration" window will pop-up. Select "Save to Current Gages" and press "Enter".
9. Move the cursor to 'Master'.
10. Fully retract the transducer, select 'Master Lo', and press "Enter".

LMI Corporation

11. Fully extend the transducer, select “Master Hi”, and press “Enter”.
12. Position the transducer into the calibration block’s flush master position. Select “Master Zero” and press “Enter”.

NOTE: The current configuration produces a negative reading when retracted beyond the nominal. To reverse the signs change the scale value in the configuration screen to -10.00.

13. The Calibration/ Mastering for flushness is now complete.

SET UP FOR GAP:

1. Connect the transducer to Gage Port 1 of the data collector.
2. Turn on the data collector.
3. Move the cursor to “Options”.
4. Select the “Configure Gages” and press “Enter”.
5. From the list displayed use the arrow keys on the data collector to choose which gage designation to configure, (i.e.: G1B G1C) and press “Enter”.
6. Type the unique gage name, (i.e.: LMI-GAP) and press “Enter”.
7. Move the cursor to “Configure” and setup as follows:
 - Type: Gap & Flush
 - Scale: 10mm (.394)
 - Zero Master: 0
 - Transducer: Low level gap gage
 - Switch: (Read)
 - Master Type: (Three Point)
 - Show Additional Parameters: (No)
8. Press the right arrow key. a “Save Gage Configuration” window will pop-up. Select “Save to Current Gages” and press “Enter”.
9. Move the cursor to “Master”.
10. Fully extend the transducer, select “Master Hi”, and press “Enter”.
11. Fully retract the transducer, select “Master Lo”, and press “Enter”.
12. Place the transducer into the calibration block’s gap mastering position. Select “Master Zero” and press “Enter”.
13. The calibration procedure for gap is now complete. This completes the calibration procedure on the LMI 770 Transducer.