


## Utility Suite Installation Instructions

### Permissions:

- Administrative rights are required to complete installation.
- All users need Read/Write permissions for the C:\Program Data\LMI Corporation folder and all subfolders.

### Requirements before installation:

- Enable .NET 3.5 on Windows 10.
  - Open the Windows 10 Control Panel.
  - Navigate to **Control Panel\Programs\Turn Windows features on or off.**
  - Click on the box next to **.NET Framework 3.5 (includes .NET 2.0 and 3.0).**
  - If the computer prompts a restart, restart the computer.




- Install VJ Sharp.
  - The library is located on the thumb drive you received with your copy of Universal Gauge Interface.
  - Double-click and follow the install prompts.

## Install Utility Suite:


- Double Click the Windows Installer.

| Name                                                                                                     | Date modified      | Type                  | Size      |
|----------------------------------------------------------------------------------------------------------|--------------------|-----------------------|-----------|
|  setup.exe              | 10/10/2025 3:04 PM | Application           | 769 KB    |
|  XU Installer Files.msi | 10/10/2025 3:04 PM | Windows Installer ... | 24,215 KB |


- Click *Yes* when the message comes up asking *Do you want to allow this app from an unknown publisher to make changes to your device?*
- Click the *Next>* button.




- Click the *Next>* button to install the software at the default location.



- Click the *Next>* button to verify you are ready to install the software.



- When the software is done installing click the *Close* button.



*Utility Suite is now installed.*